



Unpacking & Setup Instructions For Low Profile Floor Scale



Scale arrives, cut off straps & lean base against a wall. (Your small box with the Indicator/Readout may come separately via UPS or another carrier.)



Cut tape holding cardboard on bottom of base and remove cardboard. Remove three (3) phillips head screws off of each of the four (4) foot protectors. Cut off the wire ties that hold the cable and conduit under scale to free it up.



Unscrew each of the four feet 20 x 1/2 turns so that they are even and place scale on the floor. Do not drop the platform. Connect the AC Power cord to the back of the Indicator/Readout. Plug the scale base cable into the back of the Indicator/Readout. Plug the AC Plug into a 110VAC wall plug, push power switch on the back of the Indicator/Readout to turn the scale on and if the scale is not on zero, push zero button. Enjoy your scale and please refer us to any of your friends who need a quality scale at an affordable price. Thank you for your business!